



NOTIFICATION

This report contains short preliminary information about a serious incident in Switzerland without pretension to completeness and without conclusions. An investigation is in progress by the Swiss Accident Investigation Board.

Place, date and time: Geneva, 24.03.2013, approx. 14h30 LT

Aircraft:

Registration Mark: HB-IYY
Type: AVRO 146-RJ100
Operator: Swiss European Air Lines Ltd., Postfach, 4002 Basel
Owner: Swiss International Air Lines, Malzgasse 15, 4052 Basel

Pilots: 2

Passengers: 97

Flight:

Flight rules: IFR
Type of operation: Scheduled Flight
Point of departure: London-City EGLC
Point of landing: Geneva LSGG

Damage:

Crew: None
Passengers: None
Thirds: None
Aircraft: None
Ground: None

Short description of the Serious incident:

During the approach to Geneva, the cockpit crew encountered a problem with the cabin pressurization. The oxygen masks dropped in the cabin. The A/C landed normally at Geneva.